

Page 1 Of 1

Date Completed: _____ Failure Code: _____

Completed By : _____ Signature : _____

Accepted By : _____ Signature : _____

```

** Delay Codes Legend **
W=Whse   C=CrSp   T=Tag   TL=Tool   P=Plan
** Record Time Daily **           Delays

```

Step	Job Scope	MN	DY	Safety and Additional Information	Emp No	Date	Hours	Code/Hrs
1	<p>ASSIST WITH NOVATECH CARD INSTALLATION AND LINEUP OF TURBINE DURING U1 OUTAGE. 1690.061051</p> <p>*****</p> <p>JOB SCOPE:</p> <p>1. DISCUSS THE WORK TO BE DONE WITH THE UNIT OPERATOR. INFORM HIM OF ANY PROBLEMS WITH ALARMS, CONTROLS, OR INDICATIONS THAT MAY OCCUR AS A RESULT OF THIS WORK.</p> <p>2. CORRECT ALL PROBLEMS FOUND ON THIS WORK ORDER UNLESS PARTS ARE NEEDED THAT ARE NOT IN THE WAREHOUSE OR A CLEARANCE IS NEEDED TO DO THE JOB SAFELY.</p> <p>3. WORK WITH THE NOVATECH REPRESENTATIVE TO GET THE NEW TURBINE CONTROL CARDS PROPERLY SETUP AND TESTED.</p> <p>4. PLEASE NOTE ALL PROBLEMS FOUND AND ANY CORRECTIVE ACTION TAKEN TO RETURN THE SYSTEM TO NORMAL OPERATION.</p>	1	1	<p>*****</p> <p>SAFETY / ENVIRONMENTAL REQUIREMENTS:</p> <p>A. BE AWARE OF OTHER OUTAGE WORK IN PROGRESS DURING THIS WORK. DO NOT CAUSE ANY VALVE TO OPERATE WHEN SOMEONE IS IN THE VICINITY.</p> <p>*****</p> <p>ADDITIONAL INFORMATION:</p> <p>a. THE NOVATECH REP WILL BE ONSITE TO INSTALL, SETUP AND TEST SOME CARDS IN THE EHC SYSTEM. THESE CARDS WILL BE REPLACING OUR EXISTING G.E. CIRCUIT BOARDS.</p> <p>b. BILL MORGAN WILL BE THE ENGINEER OVER THIS PROJECT. HE CAN BE REACHED AT EXTENSION 6462.</p>				

**** IMPORTANT NOTICE ****

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



IP7_005538